

The following information was submitted on November 7, 2007 @ 4:05 pm:

-----

Grid Square: SD9826

Public Name: Friendly and District Rotary

Date Submitted: 7/11/07

Date Problem Observed: 20/10/07

Path From: Eringden Grange

Path To: Fairfield

Full Details: This is at the confluence of two paths at grid ref 989266. One path tunnels under another and the tunnel is in a state of collapse at one end.

An unusual feature and not sure who's responsibility it is. Council or landowner?