

Grid Square: SD9929

Public Name: liz & john

Date Submitted: 26/10/08

Date Problem Observed: 26/10/08

Path From: pecket well

Path To: midgehole

Full Details: wadsworth path/bridleway number 046 crosses over the stream in pecket well clough via Kitling Bridge (grid ref SD99407 29306).The culvert under the bridge has become choked with large stones and debris causing the stream to flood over and around the bridge every time there is heavy rainfall. This is gradually undermining the structure of the bridge and the walls supporting the footpath. Also the footpath from this point for the next 100yds is extremely affected by years of boggy leafmould now making it difficult to negotiate in any weather but particularly after rain.